

Indian Journal of Engineering

Effect of Laxmanpur Barrage on the River System - A Case Study through Multi-Temporal Satellite Remote Sensing Data

Kuldeep Pareta

Water resource Department, DHI (India) Water & Environment Pvt Ltd., Address: DLF Prime Tower, 612, Pocket-F, Okhla Industrial Area-I, New Delhi. India E-mail ID: kpareta13@gmail.com, Mobile: 9871924338

Article History

Received: 22 June 2020 Accepted: 06 August 2020 Published: August 2020

Citation

Kuldeep Pareta. Effect of Laxmanpur Barrage on the River System - A Case Study through Multi-Temporal Satellite Remote Sensing Data. Indian Journal of Engineering, 2020, 17(48), 443-449

Publication License



© The Author(s) 2020. Open Access. This article is licensed under a Creative Commons Attribution License 4.0 (CC BY 4.0).

General Note



Article is recommended to print as color digital version in recycled paper.

ABSTRACT

The Rapti River is meandering river, consisting of a variable number of meander bends, which change their locations and sizes each year. Understanding river behaviour in u/sand d/s of hydraulic structures help in their proper planning, design, and maintenance. Hydraulic analysis is made of the river behaviour in u/s and d/s of hydraulic structures like barrages and spurs as a result of sediment deposition in u/s and inadequate energy dissipation due to skewed hydraulic jump in d/s. To solve this problem, a study i.e. effects of Laxmanpur barrage on the river system has been done though multi-temporal Landsat satellite data from 1972 to 2020 provided by USGS. The river widths and sediment deposition of d/s and u/s from the Laxmanpur barrage before and after the installation of the barrage were examined. The river width before the installation of barrage is more-or-less equal in u/s and d/s. It has going to start disturbing when barrage work started in 1981. It has been taken a long time (till 2006, approx. 25 years) to re-adjust its characteristic state.







Study of hydraulic structures such as barrage, embankments, and spurs structures can provide valuable information on their influences on morphological processes in natural rivers. These structures usually used for bank protection and formation of deep navigation channel can locally create complex flow patterns, reduce flow velocities, and also increase the flood levels. Traditionally, embankments, and spurs structures are impermeable or solid structures, which are usually used to increase water depth for navigation purposes, to protect riverbank and to restore the natural river scenery (Klingeman et al., 1984; Shields et al., 2003; Wang et al., 2007). In addition to that these structures are usually generated fluid jets, leading to local scour downstream (Bormann et al., 1991; Lu et al., 2013; Guan et al., 2015; Sattat et al., 2017).

A proper understanding of the behavior of the river in the vicinity of hydraulic structures is of utmost importance in their planning, design, and maintenance in addition to the protection of the structures. They disrupt normal waterways. The flow fields that used to prevail before their construction are replaced. There is an afflux of the channel on the backwater effect upstream. Hydraulic and energy gradients are reduced. The sediment carrying capacity of the stream is reduced, leading to the deposition of sediment upward. At the bottom of the structures, erosion occurs due to high sediment leaving water with low sediment load and residual kinetic energy flow. Uncontrolled aggradation and degradation often lead to serious problems of river training (Mazumder, 2011).

2. ABOUT THE STUDY AREA

Laxmanpur barrage (Rapti barrage) is situated at 27°51′52.438" N latitude and 81°48′50.164" E longitude on Rapti River in Shrawasti district of Uttar Pradesh, India. The salient features of the Laxmanpur barrage (Rapti barrage) has been collected from CWC Water Resource Information System (CWC, 2018), and shown in Table . Location map of Laxmanpur barrage (Rapti barrage) is shown in Figure 1.




Figure 1. Location Map of Laxmanpur Barrage (Rapti Barrage), Uttar Pradesh, India

discover

Table 1 Salient Features of Laxmanpur Barrage (Rapti Barrage)

S. No.	Features Details		
1.	Name of the structure	the structure Rapti Barrage	
2.	Construction period 1981-1985		
3.	Nearest city Bahraich		
4.	District Shrawasti		
5.	State Uttar Pradesh		
6.	Name of River Rapti		
7.	Basin Ganga		
8.	Design flood (Cumec) 4990		
9.	Length of Barrage and Anicut (m) 284.5		
10.	No. of bays (i.e. number of openings) 15		
11.	Width of Bay (m) 18		
12.	Type of spillway gate Other		
13.	Crest Level (m) 125		
14.	Pond level (m) 127.7		
15.	Under sluice bay - Number 4		
16.	Gates for under sluice -Size (m) 14*18*3		
17.	Means for dissipating energy (Hydraulic) Dentated sill device		

Source: India-WRIS

3. DATA USED AND SOURCES

In this study, various basic thematic layers were created from different source including map, field study, satellite imageries and secondary data. Using ArcGIS 10.7 software tools, several maps were prepared including river bankline, hydraulic structures - embankments, spurs / studs, bridge, and barrages. Data used, and description of data sources are shown in Table 1.

Table 1 Data Used and Description of Data Sources

C 1.1	Table 1 Data Osed and Description of Data Sources			
S.No.	Data layers / maps	Description of data sources		
1.	Satellite remote sensing data	Multi-temporal, multi-spatial, and multi-spectral satellite remote sensing data from 1975 to 2019 have been downloaded for entire Rapti river basin, India from U.S. Geological Survey (USGS), Earth Explorer. Source: http://earthexplorer.usgs.gov Landsat-2 MSS: 1975 Landsat-3 MSS: 1980 Landsat-5 TM: 1988, 1990, 1998, 2004, 2006, 2007, 2008, 2009, 2010 Landsat-7 ETM+: 2001, 2011, 2012 Landsat-8 OLI: 2013, 2014, 2015, 2016, 2017, 2018, 2019		
2.	The details of Laxmanpur barrage (Rapti barrage) has been taken from India-WRIS website. Source: http://indiawris.gov.in/wris/#/			

4. RESULT AND DISCUSSION

4.1. Laxmanpur Barrage (Rapti Barrage) on Rapti River

Human impacts do not directly alter the fundamental hydraulic and geomorphic processes such as the mechanics of sediment transport, erosion, and deposition along rivers. However, human disturbance modifies the spatial distribution (pattern, extent, and linkages) and rate (accentuated / accelerated or decelerated / suppressed) of these processes, often inducing profound changes to river morphology, whether advertently or otherwise. Some processes and landscape responses now happen more often in more

places than they did prior to human disturbance. Human modifications to biophysical attributes of river systems can be direct or

due to annual flood inundations, bank erosion, high sediment load and river course shifting. Extreme flood events were reported in upstream and downstream of Laxmanpur barrage (Rapti barrage) is listed in Table 3.

Location of flood event Flood event years*/# Nepal / Upstream of Laxmanpur 1984 1989 1998 2007 2017 barrage (Rapti barrage) India / Downstream of Laxmanpur 1971 1974 1998 2001 2007 1980 2017 barrage (Rapti barrage)

Table 2. Flood Event Years of Upstream and Downstream of Laxmanpur Barrage (Rapti Barrage) (1970-2019)

With reference to several studies i.e. Bhusal (2004); Adhikari (2013); Gautam et al., (2013); Shrestha (2016) and institutional reports i.e. Osti (2008); NDRI (2012); Sanstha (2014); Devkota (2014), Nepalese have claimed that the Laxmanpur barrage (Rapti barrage) has been constructed in violation of international norms. Nepalese communities have communicated that, according to international norms the barrage can be constructed at 16.5 Km from Nepal border, while it is just about 4.5 Km from the nearest inundation point on Nepal. They have also blamed that the flood inundations, bank erosion, high sediment load and river course shifting are happening in Nepal due to Laxmanpur barrage (Rapti barrage). The inundation problem has been worsened by the construction of Laxmanpur barrage (Rapti barrage) and Kalkaluwa afflux bund (embankment) in India (due to obstruction of natural drains and flows from west Rapti river) (UNDP, 2009). I think, it is not a corrected statement, because Rapti river basin (Indian and Nepal part) is located in flood prone area. The following points are also support to our statement (Embassy of India, Kathmandu, 2000).

- The Laxmanpur barrage (Rapti barrage) is situated 4.5 Km downstream of the India-Nepal border, and the submergence is within Indian Territory.
- B. The barrage is a structure for diverting non-monsoon flows, it is not a storage reservoir, it allows for free passage of water during floods, there is no increase in the water level or inundation during such period.
- The pond level (full reservoir level) of the Laxmanpur barrage (Rapti barrage) is 127.60 m amsl, while the general ground level on the Nepalese side is 131.00 m amsl, which is higher than the pond level.
- D. The barrage is not yet operational as its gates have not been lowered.

An analysis was made on the morphological alterations, which have been taking place after the deployment of the barrage. I examined the river stretch, 10 km upstream and 10 km downstream from the Laxmanpur barrage (Rapti barrage) to analyze the possible impact of the barrage on the river system.

Multi-temporal Landsat satellite imageries for the years 1975, 1980, 1988, 1990, 1998, 2001, 2004, and 2006-2019 for the premonsoon periods were examined. The years 1975 and 1980 are the pre-installation periods while the rest of the years (1988, 1990, 1998, 2001, 2004, 2006-2019) are the post-installation periods (Figure 2).

4.2. Impact on Upstream River Morphology

In the year 1975 and 1980 (pre-installation period), the river was running in a meandering pattern shifting to the right in the upstream part. After the deployment of the barrage, the upstream river got straightened up due to the impact of the barrage as seen in the images of 1988 and 1990. In the subsequent years, the river started to take a meandering pattern again.



^{*}Flood event years after 1970, # Source: National Institute of Disaster Management (NIDM)




Figure 2. Multi-Temporal Landsat Satellite Imageries of Laxmanpur Barrage (Rapti Barrage) (1975-2019)




Figure 3. River Width during Pre-and-Post Installation Periods of Laxmanpur Barrage (Rapti Barrage)

4.3. Impact on Downstream River Morphology

Prior to the construction of the barrage, the river took a 90° turn to the right at about 5 km downstream from barrage. After deployment of the barrage, the river moved to the left, but it could not move further to left due to the presence of signification riparian vegetation and afforestation work (as evident from green and geometric pattern in satellite imageries in 1988 image). After

the obstruction by the riparian vegetation, the river meandered in a zigzag pattern after passing the vegetative zone approx. about 5 km downstream. In the subsequent years, the downstream river moved gradually away from the vegetation zone, but the downstream meandering continues but by 2017 the river became less meandering.

The river widths of downstream and upstream from the Laxmanpur barrage (Rapti barrage) before and after the installation of the barrage were examined. The river width before the installation or construction of barrage is more-or-less equal in u/s and d/s. It has going to start disturbing when barrage work started in 1981. It has been taken a long time (till 2006, approx. 25 years) to readjust its characteristic state. After 2006, the balance of river width in u/s and d/s is more-or-less equal (Figure 3), because geomorphic response times following the emplacement of river engineering works depend on the types of works installed and the extent to which they alter flow and stream power, sediment supply and vegetation cover. It may take 20 to 100 years to attain this new characteristic state.




Figure 4. Sediment Deposit in u/s and d/s of Laxmanpur Barrage (Rapti Barrage)

I have also examined the sediment deport in downstream and upstream from the Laxmanpur barrage (Rapti barrage), and I have found that the deposition of sediment is disturb from 1981 to 2005 (approx. 25 years). In that period deposition is more in upstream and the reverse in downstream. I have notices that the sediment deposition pattern in u/s and d/s is more-or-less equal from 1975 to 1980 (before installation of the barrage), and from 2006 to 2019 (Figure 4), that is also support our above stated statement.

4.4. What Happen when Laxmanpur Barrage (Rapti Barrage) will Operational?

The construction of Laxmanpur barrage (Rapti barrage) was completed in 1986, but it has not been operated till date. When the Laxmanpur barrage (Rapti barrage) will start the operation, it will affect the river morphology in upstream and downstream of barrage. In upstream of barrage, It will reducing velocities of water, due to this silt and sediment will accumulate at a higher rate, lowering the river height and decreasing the river speed leading to lateral expansion of the river or widening of the channel (braiding of river streams), suspended silt particles in the river water settle down.Relatively silt and sediment free water will be released through the spillway have the energy to move sediment in downstream, causes erosion in downstream. This 'hungry water' expends its energy by eroding the channel bed and banks. Bed incision and river widening may reduce over the timeframes ranging from 20 to over 100 years, when river will re-adjust its new characteristic state.

5. CONCLUSION

In this paper, remote sensing and GIS techniques have been used intensively. The free Landsat series satellite imageries from 1972 to 2020 provided by USGS is now used all over the world. With this type of satellite imagery, we can generate and analyze the time series data of the last 50 years. These datasets have been used for study of effect of Laxmanpur barrage (Rapti barrage) on the river system. The river widths and sediment deport of d/s and u/s from the Laxmanpur barrage (Rapti barrage) before and after the installation of the barrage were examined. The river width before the installation or construction of barrage is more-or-less equal in

u/s and d/s. It has going to start disturbing when barrage work started in 1981. It has been taken a long time (till 2006, approx. 25 years) to re-adjust its characteristic state. After 2006, the balance of river width in u/s and d/s is more-or-less equal, because geomorphic response times following the emplacement of river engineering works depend on the types of works installed and the extent to which they alter flow and stream power, sediment supply and vegetation cover. It may take 20 to 100 years to attain this new characteristic state.

Funding:

This study has not received any external funding.

Conflict of Interest:

The author declares that there are no conflicts of interests.

Peer-review: External peer-review was done through double-blind method.

Data and materials availability: All data associated with this study are present in the paper.

REFERENCE

- 1. Adhikari BR. Flooding and inundation in Nepal terai: issues and concerns. Hydro Nepal. 2013: 12: 59-65.
- Bhusal JK. Consequences of river training structures a case of Laxmanpur barrage and afflux bunds near Indo-Nepal border. Journal of Hydrology and Meteorology, SOHAM-Nepal. 2004: 1(1): 1-5.
- 3. Bormann NE, and Julien PY. Scour downstream of gradecontrol structures. Journal of Hydraulic Engineering. 1991: 117: 579-594.
- CWC. Water Resources Information System (WRIS). http://cwc.gov.in/water-resources-information-system-wris. 2018.
- Devkota RP. Flood adaptation strategies under climate change in Nepal - A socio-hydrological analysis. Ph.D. Thesis, University of Southern Queensland. 2014.
- Gautam DK and Phaiju AG. Community based approach to flood early warning in west Rapti river basin of Nepal. Journal of Integrated Disaster Risk Management. 2013: 3(1): 155-169.
- Guan D, Melville BW, and Friedrich H. Live bed scour at submerged weirs. Journal of Hydraulic Engineering. 2015: 141: 401-407.
- Klingeman PC, Kehe SM, and Owusu YA. Streambank erosion protection and channel scour manipulation using rockfill dikes and gabions. Water Resources Research Institute Technical Report WRRI-98. Oregon State University, Corvallis, OR. 1984.
- Lu JY. Hong JH. Chang KP, and Lu TF. Evolution of scouring process downstream of grade-control structures under steady and unsteady flows. Hydrological Processes - Wiley Online Library. 2013: 27: 2699-2709.
- 10. Mazumder SK. River behaviour upstream and downstream of hydraulic structures. Semantic Scholar. http://profskmaz umder.com/PDF/Ref_75.pdf. 2011.

- 11. NDRI. Assessment of flood inundation in lower west Rapti basin under the effect of climate change. Nepal Development Research Institute (NDRI), Kathmandu, Nepal. 2012: 1-113.
- Osti R. A feasibility study on integrated community-based flood disaster management Banke district Nepal, phase-1 baseline study. International Centre for Water Hazard and Risk Management (ICHARM), Public Works Research Institute (PWRI). 2008: 4122(11): 1-111.
- Sanstha JV. Climate vulnerability and gap assessment report on flood and drought (lower Rapti river Basin case study). Global Water Partnership (GWP), Nepal and Jalsrot Vikas Sanstha (JVS). 2014: 1-45.
- Sattar AMA, Plesiński K, Radecki-Pawlik A, and Gharabaghi
 Scour depth model for grade-control structures. Journal of Hydro-informatics. 2017: 20: 117-133.
- Shields JFD, Knight SS, Morin N, and Blank J. Response of fishes and aquatic habitats to sand-bed stream restoration using large woody debris. Hydrobiologia. 2003: 494(1-3): 251-257.
- Shrestha HM. Naumore storage project should be the last resort of development on the main course of Rapti (West), Nepal. Hydro Nepal. 2016: 18: 1-5.
- UNDP.ISDR global assessment report on poverty and disaster risk. United Nations Development Programme (UNDP), Kathmandu, Nepal. 2009.
- 18. Wang H, Yang Z, Saito Y, Liu JP, Sun X, and Wang Y. Stepwise decreases of the Huanghe (Yellow River) sediment load (1950-2005), impacts of climate change and human activities. Global and Planetary Change. 2007: 57: 331-354.
- Embassy of India, Kathmandu. Annex 27, Press Release of the Embassy of India, Kathmandu (Nepal) on Laxmanpur Barrage. https://link.springer.com/content/pdf/bbm%3A97 8-1-4020-8403-4%2F1.pdf. 2000: 480.